Provincial Disaster Management Authority
PEOC, Quetta, Balochistan.

No. PDMA/ PEOC /010/2022 Dated Quetta **Monday,10th January2022**

Daily Situation Report

Weather Situation Overview (Source PMD)

Weather Prevailed during
Last/Past- 24hrs

- Mainly cold and dry weather remained in most parts of the province.
- **Minimum Temperature** recorded. District **Ziarat :(-12.4)**
- **Maximum Temperature** recorded. District **Gawadar & Lasbella: (22.5)**


Weather Forecast
Next/upcoming-24hrs

- Mainly cold and dry weather is expected in most parts of the province, While very cold and frosty conditions in Central and hilly parts of the province.


Weather Forecast
Next / upcoming 48 - 72


- Mainly cold and dry weather is expected in most parts of the province, While very cold and frosty conditions in Central and hilly parts of the province.

Weather Chart
Districts of Balochistan



Call Center Report





LEVEL OF DAMS/RIVERS			
DAM/RIVER	DISTRICT	SPILWAYS LEVEL	CURRENT LEVEL
Hub Dam.	Lasbella Hub.	350ft.	331.03ft.
Mirani.	Turbat.	244ft	243.70 ft
Shadi Kaur Dam.	Gawadar.	36ft.	30.06ft
Sabkzai Dam.	Zhob.	94ft.	41.06ft.
Sawar Dam.	Gawadar.	35ft.	25.04ft.
Akara Dam	Gawadar	80ft.	37.02ft

LEVEL OF CANALS				
CANAL	INDENT	GUAGE	DISCHARGE	SHORTFALL
Pat Feeder canal	6700 cusec	9.8 ft	5097 cusec	1603 cusec
Khirther canal	2400 cusec	7.5 ft	1675 cusec	725 cusec
Uch canal	700 cusec	5.0 ft	200 cusec	500 cusec
Manuthi Canal	600 cusec	7.0 ft	300 cusec	300 cusec

Provincial Disaster Management Authority
PEOC, Quetta, Balochistan.

- As per the information of Pakistan Metrological Department (PMD) Dated 03 Dec 2021, Strong Westerly Weather System is likely to enter western/upper parts of the country likely to grip most parts of the country and may persist till 09 Jan.
- According to Winter Contingency Plan, PDMA Balochistan enable Emergency Response Center at Kanmehterzai to facilitate 200 people of most vulnerable areas in any disastrous situation. Although all District Disaster Management Authorities are directed to stay vigilant and took safety measures.
- Provincial Emergency Operation Center at PDMA office, Quetta is working round the clock 24/7and directed to coordinate with Local Administration / DDMAs and other line department for timely response.

FLOOD SITUATION TILL NOW
Table No: 01

Dated: 04-January-2022	
• Urban Flood Reported At Kech, Damages Reported, Assessment Going on. • Kaniro Dam Spillway Damages (8900 Cs).	• Flood Reported at Chaman, Damages Reported, Assessment Going on. • 04 Jan 2022: Sawar Dam Protection Bond has been damaged at different RDS (27500 Cs)

- The PDMA Balochistan timely respond on Local Administration / DDMAs demand and dispatched relief items for flood /snowfall affected areas are as reflected in *Table No: 02*

FLOOD RELIEF ITEMS
Table No: 02

NON-FOOD ITEMS		
S#	**ITEMS**	**QUANTITY**
01	Plastic Mats	1265
02	Kitchen Set	1180
03	Charpoy	690
04	Plastic Bucket	639
05	Generator (15kv)	2
06	Quilts	2050
07	Water Cooler	1050
08	Solar Light	980
09	Tarpaulin	2640
10	Electric D-Watering Pump	04
11	Water Tank (400gln)	50
12	Tent	1690
13	Blankets	4675
14	Pillows	15
15	Gas Cylinders	930
16	Jerry can	905
17	Life Saving Jackets	100
18	First Aid Kit	1500
19	Fibre Boat (23,13 ft + Engine)	2
FOOD ITEMS		
01	Food Packets	100
02	Sugar(kg)	3500
03	Grams(kg)	3900
04	Rice(kg)	3250
05	Tea(kg)	335
06	Salt(kg)	13000
07	Mineral Water	1000

- As per initial damage report received from line department / local administration is as reflected in table No: 03. However damages will be updated timely after completion of Initial Damage Assessment Report (IDAR).

DAMAGES REPORTED TILL NOW
Table No: 03

Dated:04 Jan 2022	
• Sawar Kaur Pasni- Protection Bunds has been damaged from different RDs	• Kanero Kaur- Spill Way Damaged

	Dam	Height	Catchment Area(Sq.km)	Storage Capacity(Aft)	Storage During the Recent Flood (Aft)
01	Dosi Dam (Pasni)	41.5	144.96	16000	16000
02	Shenzani Dam	42.50	43.60	17800	-
03	Sawar Dam	55.0	1800	45000	45000

04	Bellar Dam	48.0	243	10588	10588
05	Kannero Dam	51.0	97.5	930	930
06	Rumro Dam	60.0	243.84	6585	6585
07	Mokola Dam	50.0	64.02	396	396

- As per initial damage report received from line department / local administration is as reflected in *Table No: 03*. However damages will be updated timely after completion of Initial Damage Assessment Report (IDAR).

DAMAGES REPORTED TILL NOW
Table No: 04

S#	Sub Divisi- on	Rainfall	Sub Tehsil Ward/UC	Causalitie	Protect Ions walls	House Boundary walls	Karizat	Water Sups	Health Facility	Educational	Agricultural Corps	Others
1	Turbat	24.1 mm	Absor	-		25	-	Survey in progres s	-	Survey in progress	Survey in progress	Survey in progres s
			Nasirabad	-		20	-	-	-	-do-	-do-	-
2	Dasht		Balnigore	-	1 2	65	-	-	BHU Kashap	-do-	-do-	-
3	Tump	65.00 mm	Tump	-		3	-	-	BHU Gawak BHU Redeer	-do-	-do-	-
			Pull Abad	-	1	5	-	-	-	-do-	-do-	-
			Dazin	-	2	5	-	-	-	-do-	-do-	-
			Asia Abad	-		7	-	-	-	-do-	-do-	-
			Balicha	-	1	6	-	-	-	-do-	-do-	-
			Libana-koh-dem	-	9	5	-	-	-	-do-	-do-	-
4	Buled a	27.47		-	Survey in progre ss	Survey in progress	-	-	-	-do-	-do-	-
	Total			-	2 5	141	-	-	-			-

FLOOD AFFECTED AREA GAWDAR DAMS REPORT
Table No: 05

Da m		Heigh t	Catchment Area(Sq.km)	Storage Capacity(Aft)	Storage During the Recent Flood (Aft)
01	Dosi Dam (Pasni)	41.5	144.96	16000	16000
02	Shenzani Dam	42.50	43.60	17800	-
03	Sawar Dam	55.0	1800	45000	45000
04	Bellar Dam	48.0	243	10588	10588
05	Kannero Dam	51.0	97.5	930	930

06	Rumro Dam	60.0	243.84	6585	6585
07	Mokola Dam	50.0	64.02	396	396

- The PDMA Balochistan has deployed its Heavy Machinery on most vulnerable areas to ensure smooth flow of traffic and to enable land communication. Details are reflected in *Table No: 06*

DAMAGES REPORTED TILL NOW
Table No: 06

SNO.	LOCATION	Nos	MACHINERY
01	KHOJAK TOP	01	SNOW REMOVER
02	QILLA SAIFULLAH	01	SNOW REMOVER
03	MUSTUNG LAKPASS	02	SNOW REMOVER
04	ZIARAT	03 01	SNOW REMOVER SNOW BLOWER
05	KAN-MEHTERZAI	02 02	SNOW REMOVER TRACTOR

- PDMA BALOCHISTAN is working round the clock 24/7 to ensure the safety and security of Public – Private. Daily activities are as reflated in *Table NO: 07*

FLOOD AFFECTED AREA GAWDAR DAMS REPORT
Table No: 07

DATE	DAILY ACTIVITIES
04 Jan 2022	• 2.0 inches snowfall reported at Ziarat. Levies teams are deployed at different points for spraying de-icing salt to make roads trafficable. Roads are opened by PDMA Machinery. • PDMA Snow blowers opened roads of Kan Mehtarzai. • Urban Flood reported at Gawadar and Chaman , where PDMA along with DDMA Rescue people and Distribute Relief items However Damages Reported.
05 Jan 2022	• PDMA along with DDMA Relief and restoration activities in district kech after heavy rainfall. • Kannori Dam reported damage of Protection wall of bund, whereas Assessment is going on. • Sawar Dam Spilways damage reported, whereas Assessment is going on
06 Jan 2022	• Snow removal work ongoing by NHA and PDMA Team at Khojak Area with heavy machinery. • PDMA Snow blowers opened Kan Mehtarzai roads.
07 Jan 2022	• PDMA Snow blowers opened Kan Mehtarzai roads. • Snow removal work ongoing by PDMA Team at Khojak Area with heavy machinery. • Snow has accumulated on the main roads from Kach to Ziarat and from Ziarat to Chothair. All the vehicles that were stuck in the snowfall were evacuated. Roads are open only for light vehicles. Teams are spraying de-icing salt. Levies force and PDMA staff are engaged in rescue Activities.

(ASGHAR ALI JAMALI)
DEPUTY DIRECTOR/ADMINISTRATOR
PEOC, PDMA BALOCHISTAN